

Measurements

Sp1	49.1 °F
Sp2	37.9 °F
Sp3	46.1 °F

Parameters

Emissivity	0.8
Ref. temp.	29 °F

Temperature Change noted below:


Trans 1 (Sp1)
 Trans 2 (Sp2) 11.2 degrees

Trans 1 (Sp1)
 Trans 3 (Sp3) 2.9 degrees

Trans 2 (Sp2)
 Trans 3 (Sp3) 8.30 degrees

Recommended Action:
 Check load balance on
 Transformer 2 or run diagnostic
 test on Transformer 2.

12/29/2017 3:11:49 AM



FLIR0042.jpg

FLIR C3

720078407

12/29/2017 3:11:49 AM



FLIR0042.jpg

FLIR C3

720078407

Branden Cook
 1168 West 500 North
 Centerville, UT 84014
 branden@norpow.com